Plaintiffs' Exhibit 11

GIORDANO ASSOCIATES, INC

Established 1978

71 High Street East Haven, Connecticut 06512 (800) 469-7477 FAX (203) 469-6409

Macdonald, Illig, Jones & Britton Attorney Terry Jones 100 State Street Erie, PA 16507

RE: Dr. Borden

Dear Attorney Jones:

I have reviewed the building estimate submitted on behalf of Amica Insurance which was prepared by G.S. Jones. I found the estimate to be more logical and detailed then Amica's first offer. Below are some areas of concern. I went room by room to make it easier to follow.

Basement General:

- Plastic sump pump pit, with hosing, and pump. If part of plumbing estimate I need detailed breakdown to verify.
- With the extent of heat and items melted to the floor I would like to keep the basement floor open for inspection once the debris is removed. The floor will require exposy sealing to rid it of smell, even under the carpet.
- Locksets on doors

Left front basement-Finished:

 With the extent of heat and items melted to the floor I would like to keep the basement floor open for inspection once the debris is removed. The floor will require exposy sealing to rid it of smell, even under the carpet.

Crawl Spaces:

- Replace vapor barriers on the dirt floors.
- Replace the smoke detectors.



Steps to kitchen:

- Sub floor on landing
- Oak floor on landing
- Base trim on landing
- There is a sill around the entire wall perimeter, which is the top of the basement brick wall. This had a top plate piece of finished pine with a chair rail tight to the bottom.
- Wall insulation 2 walls

Kitchen:

- There was a 2 pc base trim (3.5 plus a shoe)
- Beams were wrapped in a pine 1 x 10 on sides and a 1 x 8 on bottom (see my estimate for measurements). I assume the figure in the estimate is for the beam only.
- Cased opening
- Scaffold and drywall charge to sheetrock the skylight chase.
- Painting charge for skylight chase
- Does countertop price include counter tops? The tops are Corian and the price does not appear to include them.
- The appliances were all built in. Need to add top quality appliance plus all electrical and plumbing hook ups: Dishwasher, 2 wall ovens, cabinet hanging microwave, Water purifier (Kenmore), electric Stove 32 inch, Refrigerator with water and ice.
- No allowance for kitchen sink. If part of a plumbing bid item need to see breakdown to verify.
- All cabinets and draws had child safety latches installed.
- Size walls before papering.
- Crown molding
- Curtain rods installation.
- Locksets on doors.
- There is no allowance for the kitchen sink. I see the piping allowance but no fixtures

Mudroom:

- There was a small closet at the end of the mud room on the right. The closet is on page 14 of my estimate and missing from this estimate.
- There is a 2 pc base trim
- Locksets on doors.
- Heat registers
- 2 Bifold doors on closet (pantry)
- Exterior doors there are 2
- Pantry shelving was 5/8 cabinet grade. There was 28 if and a closet pole

Powder Room:

- This room was wallpapered with a border not painted.
- There is a 2 pc base trim
- Heat registers
- Medicine cabinet
- Locksets

Garage:

- Disagree with partial sheet rock
- Garage door not addressed
- Ceiling is textured if only doing partial ceiling we need to scrape and prep balance
- Closet Doors are unfinished wood and will retain the odor. These are bifolds
- Closet shelving is unfinished wood as well. 5/8 cabinet grade
- Exterior door

Studio:

- Cathedral ceiling requires scaffolding
- Beams were wrapped in a pine 1 x 10 on sides and a 1 x 8 on bottom (see my estimate for measurements). I assume the figure in the estimate is for the beam only.
- Heat registers